Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 9/11/2012, 9/12/2012, 9/13/2012 Man Day	
Inspection Unit: Springfield	
Location of Audit: Springfield	
Exit Meeting Contact: Mark Mancewicz	
Inspection Type: Standard Inspection - Field Audit	
Pipeline Safety Representative(s): Charles Gribbins	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	

Headquarters Address Information:	300 Liberty	
	Peoria, IL 61602	
	Emergency Phone#:	
	Fax#:	
Official or Mayor's Name:	Ron Pate	
	Phone#: (217) 424-6518	
	Email:	
Inspection Contact(s)	Title	Phone No.
Mark Mancewicz	Superintendent of Operations	

Category Comment:	
Customer meters were viewed at the following locations:	
Security Bank 2 meters this location	
430 E Monroe 4 meters	
East Monroe 3 meters	
414A E Monroe	
414 1/2 E Monroe	
414B E Monroe	
Postal Office Monroe	
213 5th Street	
215 5th Street	
217 5th Street	
Brick house leak on meter set	
Old Osco Building 2 meters	
518 5th Street 5 meters foreign contact to meter set	
Prairie Archives	
Robbie's Restaurant	
Indian Hills Subdivision;	

Status

CUSTOMER METER & REGULATOR

damage. 192.355(b)(1)	ls the customer regulator vent rain and insect resistant?	s to prevent vehicular Satisfactory
	Is the customer regulator vent rain and insect resistant?	Satisfactory
	Is the customer regulator vent rain and insect resistant?	Satisfactory
	Is the customer regulator vent rain and insect resistant?	Satisfactory
	Is the customer regulator vent rain and insect resistant?	Satisfactory
	Is the customer regulator vent rain and insect resistant?	Satisfactory
	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
192.355(b)(1)	Is the customer regulator vent rain and insect resistant?	Satisfactory
	To the case of the galaxier contrains and the case of	- Cationation y
General Comment:		
The vent screens were inspe	ected and found to be rain and insect resistant.	
•		
192.355(b)(2)	Is the customer regulator vent located where gas from the vent escapes freely into the atmosphere and away from building openings?	Satisfactory
General Comment:	and annual production and annual grant gra	
General Comment.		
All meter set locations inspe	cted were located where gas could vent freely into the atmosphere and away form building openings.	
192.355(b)(3)	Is the vent protected from damage caused by submergence in areas of flooding?	Not Applicable
. , , ,	is the vent protected from damage caused by submergence in areas of hooding?	Not Applicable
General Comment:		
In the areas inspected the op-	perator does not have any meter sets located in an area prone to flooding.	
192.357(a)	Is the customer meter and regulator installed to minimize anticipated stresses upon connecting piping?	Satisfactory
0	aport controcally pipility.	
General Comment:		
Of the meters listed in the re	port it did not appear that there was any stress on the connecting piping.	
192.357(d)	Is a customer regulator that might release gas vented to the outside atmosphere?	Satisfactory
General Comment:		
All customer regulators are I	ocated outside the structures and can vent safely to atmosphere	

Unless otherwise noted, all code references are to 49CFR Part 192.

If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

192.359(a)	Is the meter operating pressure within the allowable limits of the meter case rating?	Satisfactory
General Comment:	·	
The meters were found to	have operating pressure of 5#, 10# 20 #, and 25# which is marked on the case of the meter.	
192.365(a)	Is the service line valve upstream of the regulator or meter?	Satisfactory
General Comment:	<u> </u>	
At all locations the service	e line valve was found to be upstream of the regulator and meter set.	
192.365(c)	Is the underground service line valve located in a curb box or standpipe that allows for ready operation?	Not Applicable
General Comment:	<u> </u>	
At the location of the cust	omer meter inspections staff did not encounter any curb boxes or standpipes with the valves located in them).
192.727(d)	When service to the customer has been discontinued has the proper method been utilized to prevent unauthorized usage?	Satisfactory
General Comment:	<u> </u>	
Staff noted at some locati	on the when service to a meter was discontinued that a pin locking device was used to secure the lock wing	on the meter set.
Staff noted at some locati	on the when service to a meter was discontinued that a pin locking device was used to secure the lock wing CATHODIC PROTECTION	on the meter set. Status
Staff noted at some location		
Category Comment:	CATHODIC PROTECTION Dipe to soil reading were obtained: Deer composite riser -1.025 volts	

The operator's distribution system is protected by anodes. This meets Appendix A, a negative (cathodic) voltage of at least 0.85 volt, with reference to a saturated copper-copper sulfate half cell. Determination of this voltage must be made with the protective current applied, and in accordance with sections II and IV of this appendix.

	DAMAGE PREVENTION	Status
In Springfield's downto under the service valve	wn business district staff found a riser at 528 E Adams, meter number 03671781 that had severe atmospheri e.	c corrosion, on the riser just
	division were found several risers with some type of disbonded coating on the risers. A review of the atlas pag of some type action that needed to be taken in the area of atmospheric corrosion.	e indicated there were
Regulating Station XS2	206, with some corrosion found at the soil to ground interface.	
During the field inspec	tion conducted in the Springfield Service area staff found the following conditions associated with atmospherio	c corrosion;
Issue Comment:	1	l
192.479(c)	Is the pipeline free of corrosion or pitting?	Unsatisfactory
Most of the above grou	und piping was painted or coated.	
General Comment:		1
192.479(a)	Is the above ground piping coated or painted as required?	Satisfactory
Staff did not inspect ar	ny casing as part of this inspection.	
General Comment:		1
192.467(c)	Were casings installations tested for electrical isolation?	Not Checked
	ulating meter spuds and insulating service valves as a means of electrical isolation.	
General Comment:	flange?	
192.467(a)	Is electrical isolation provided by use of insulated meter spud, valve, union, or	Satisfactory
The operator's system	does not contain critical/or non-critical bonds.	
General Comment:		· L
192.465(c)	Were critical/non critical bonds tested?	Not Checked
During this inspection	staff did not inspected any distribution system that contained isolated sections of main or isolated service lines	5.
General Comment:		THE CHICAGO
192.465(a)	Were isolated mains/services tested?	Not Checked
	have any rectifiers on the distribution system.	
General Comment:	were rectiner installations inspected:	Not Checked
192.465(b)	Were rectifier installations inspected?	Not Checked
General Comment:	ent section above for the pipe to soil reading taken during the field audit.	
192.465(a)	Were pipe to soil readings taken?	Satisfactory

192.614	Does the operator have a valid notification of planned excavation activities?	Not Checked
General Comment:		
At the time of this inspe	ection staff did not inspect any planned excavation activities.	
ADM. CODE 265.40(a)	Did the operator complete the locating activities in the specified timeframe?	Not Checked
General Comment:		
At the time of this inspe	ection staff did not inspect any planned excavation activities.	
192.614(c)(5)	Were temporary markings made in accordance with the operator's Operation and Maintenance Manual?	Not Checked
General Comment:		
At the time of this inspe	ection staff did not inspect any planned excavation activities.	
192.707(a)(1)	Are line markers placed and maintained as close as practical over each buried main and transmission line located at each crossing of a public road and railroad?	Satisfactory
General Comment:		
The operator had place other locations on the o	ed line markers at various locations over the distribution lines. Line markers were verified at the regulator statio operator's system.	n of XS206 and several
192.707(a)(2)	Are line markers placed and maintained as close as practical over each buried main and transmission line located wherever necessary to identify the location of the transmission line or main to reduce the possibility of damage or interference?	Satisfactory
General Comment:		
The operator place line	markers at various locations where it was necessary to identify the pipeline.	
192.707(c)	Are line markers placed and maintained as close as practical over each buried main and transmission line located above ground?	Satisfactory
General Comment:		
Line markers must be	placed and maintained along each section of a main and transmission line that is located above ground in an a	area accessible to the public.
192.707(d)(1)	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line marker: The word "Warning," "Caution," or "Danger" followed by the words "Gas (or name of gas transported) Pipeline" all of which, except for markers in heavily developed urban areas, must be in letters at least 1 inch (25 millimeters) high with ¼ inch (6.4 millimeters) stroke?	Satisfactory
General Comment:		
The line markers conta	in the following wording Warning or Danger and have lettering of at least 1 inch and 1/4" stroke.	
192.707(d)(2)	Do the operator's line markers contain the following information: The following must be written legibly on a background of sharply contrasting color on each line	Satisfactory

	Г	
	marker: The name and phone number (including area code) of the operator where the operator can be reached at all times?	
General Comment:		
The line markers are of con	trasting colors of yellow and black, and contain a number that the operator can be contacted 24 hours a da	y.
PRESSUR	RE LIMITING AND REGULATING DEVICES (MECHANICAL)	Status
Category Comment:		
Staff observed a maintenand The station.	ce inspection of pressure station at Franklin Park; station #XS206. All Ameren Illinois procures were follow	ed during the inspection o
192.739(a)(4)	Was each pressure limiting station, relief device (except rupture discs), and pressure regulating station and its equipment subjected at intervals not exceeding 15 months, but at least once each calendar year, to inspections and tests to determine that it is properly installed and protected from dirt, liquids, or other conditions that might prevent proper operation.?	Satisfactory
General Comment:		
The following station was in	spected for the following items: protection from dirt, liquids that could prevent proper operation.	
192.317(b)	Is each above ground transmission line or main protected from accidental damage by vehicular traffic or other similar causes?	Satisfactory
General Comment:	<u>'</u>	
The operator's station XS20	6 was protected from vehicular damage by distance from the road and fencing.	
192.741(a),192.741(c)	Were telemetering and/or recording gauges inspected for abnormally high or low pressure indications?	Not Checked
General Comment:		
This station XS206 does no	t have a pressure chart recorder or a recording gauge. The 90 psi line does have chart records located at o	other locations.
192.743(a)	Is overpressure protection provided on the pipeline down stream of the take point?	Not Applicable
General Comment:		
The over pressure protection	n for this line is provided by the transmission side of Ameren Illinois.	
192.199(d)	Did the pressure relief or pressure limiting devices inspected to determine if the support was made of noncombustible material?	Satisfactory
General Comment:		
had to be disassembled and	n relief device and it was tested during the inspection. During the inspections the relief device would not re If corrective action taken to remove debris from the seat area, wants this was done the relief device was purelief device was put back into service.	
92.199(e)	Did the pressure relief or pressure limiting devices inspected to determine if the discharge stacks, vents, or outlet ports were designed to prevent accumulation of water, ice, or snow, and located where gas can be discharged into the atmosphere without undue hazard?	Not Applicable
General Comment:	<u>'</u>	

MARKING OF MATERIAL	Status
e distribution system not the transmission system.	
<u>'</u>	
Is pre-tested transmission pipe inventory maintained for use in an emergency?	Not Applicable
e distribution system not the transmission system.	
<u></u>	
Were the valves inspected accessible?	Not Applicable
e distribution system not the transmission system.	
	Not Applicable
TRANSMISSION	Status
perator's equipment for calibration the last calibration date was 5/24/2012. The unit identification number was SN	<i>l</i> 21383.
The second of the second secon	Cationactory
	Satisfactory
e odorization equipment.	
vvas tile Odolization equipment and tank levels inspected?	Not Checked
· · · · · · · · · · · · · · · · · · ·	
Ne Stainer and Laboured an adar intensity test in the Indian Hills Sybdivision. The adar was detectable at	240/ gas and air mistur
Was the odor intensity level readily detectable at or below 1/5th LEL?	Satisfactory
	Status
	-
Were the valves inspected accessible?	Satisfactory
VALVE MAINTENANCE	Status
re there is no stop valve to secure.	
Was each valve, designed to isolate the system under protection from its source of pressure, secured to prevent unauthorized operation of any stop valve that will make the pressure relief valve or pressure limiting device inoperative?	Not Applicable
	make the pressure relief valve or pressure limiting device inoperative? **Rethere is no stop valve to secure.** **VALVE MAINTENANCE** Were the valves inspected accessible? **Were the valves inspected accessible?** **ODORIZATION OF GAS** Was the odor intensity level readily detectable at or below 1/5th LEL? **International Comment of the Indian Hills Subdivision. The odor was detectable at or was detectable at or below 1/5th LEL? **Was the Odorization equipment and tank levels inspected?** **Was the Odorization equipment calibrated as required?** **Was the operator's equipment calibrated as required?** **PRANSMISSION** Are transmission valves protected from tampering or damage?** **Were the valves inspected accessible?** **Were the valves inspected accessible?** **Is pre-tested transmission pipe inventory maintained for use in an emergency?** **We distribution system not the transmission system.** **Is pre-tested transmission pipe inventory maintained for use in an emergency?** **Is distribution system not the transmission system.**

192.63(a)	Does the operator's components and pipe contain the required markings?	Not Checked
General Comment:		
Staff was inspecting	the distribution system and did not check the operator's components or piping inventory.	
	OPERATOR QUALIFICATION	Status
Was a PHMSA F	orm 15 Operator Qualification Field Inspection Protocol Form completed?	Yes
General Comment:		
Staff conducted seve	ral Operator Qualifications using PHMSA form 15, see those separate inspection checklist.	